

PRODUCT INFORMATION

Style: 628FR

Sizing: Size Part #
 Large 628FR

Registered Brand Name:
Classification: Heat Resistant



PRODUCT DESCRIPTION

Description: Blue Terry Cloth with Duck Cuff
Color: Blue
Material: Terry Cloth
Weight: Heavy
Cuff: Duck gauntlet cuff
Heat Resistance: 250°F

Sold by: Dozen
Packaging (Inner Pack): 6 Pairs
Packaging (Case Pack): 60 Pairs

FLAME TESTING INFORMATION

Test Method: ASTM F1358-08
Test Results: ANSI Level 4

WASHING INSTRUCTIONS

Machine wash in warm water with mild detergent or soap for 10-15 minutes. Water temperature should not exceed 160°F (71°C). Rinse in cold water. Tumble dry for 10-15 minutes, not exceeding 150°F (67°C). Terry products may require additional drying time. Do not use bleach or dry cleaning solution.

CAUTION

The degree of heat resistance a glove may offer is directly related to the duration of exposure and weight of the object being handled.

Wells Lamont Industrial
Toll-Free 1.800.247.3295 www.wellslamontindustrial.com