

PRODUCT SPECIFICATION SHEET

PRODUCT INFORMATION

Style: 5601

Sizing:	<u>Size</u>	<u>Part #</u>	<u>Overedge</u>
	XSmall	5601XS	Green
	Small	5601S	Yellow
	Medium	5601M	Blue
	Large	5601L	White
	XLarge	5601XL	Orange
	XXLarge	5601XXL	Black



Classification: Cut Resistant

PRODUCT DESCRIPTION

Description: Gray High Performance Cut Glove
Gauge: 15 Gauge
Material: Combination of High Performance, Durable Fibers and Stainless Steel
Packaging (Inner Pack): 6 Pieces
Packaging (Case Pack): 72 Pieces

CUT PROTECTION PERFORMANCE INFORMATION

Test Method: ASTM F2992-15
Test Results: 4,147 grams
ANSI Level A7

ABRASION PROTECTION PERFORMANCE INFORMATION

Test Method: ASTM D3884-09
Test Results: ANSI Level 3, 1350 Cycles

WASHING INSTRUCTIONS

Remove all large particles. Rinse with cold water then machine wash in warm water with mild detergent or soap for 10-15 minutes. Water temperature should not exceed 160°F (71°C). Rinse in cold water. Tumble dry for 10-15 minutes, not exceeding 150°F (67°C). A diluted bleach solution may be used (5.25% sodium hypochlorite or 1:10 household bleach).

CAUTION

Gloves are cut resistant but are not cut or puncture-proof. Do not subject to high-speed, serrated blades or intentional slashings.

Wells Lamont Industrial
Toll-Free 1.800.247.3295 www.wellslamontindustrial.com