

PRODUCT SPECIFICATION SHEET

PRODUCT INFORMATION

Style: 5600

Size Part # **Glove Color** Sizing:

> XSmall 5600XS Yellow Small 5600S Orange Medium 5600M Blue 5600L **Purple** Large XLarge 5600XL Green XXLarge Brown 5600XXL

XXXLarge 5600XXXL Black

Classification: **Cut Resistant**

PRODUCT DESCRIPTION

Description: Multi Color High Performance Cut Glove

Gauge 15 Gauge

Material: Combination of High Performance, Durable Fibers and Wire

CFR 21 - Approved for Food Contact

Packaging (Inner Pack): 6 Pieces Packaging (Case Pack): 72 Pieces

CUT PROTECTION PERFORMANCE INFORMATION

Test Method: ASTM F2992-15 Test Results: 5270 grams

ANSI Cut Level A8

ABRASION PROTECTION PERFORMANCE INFORMATION

Test Method: ASTM D3884-09 Test Results: 1350 Cycles

ANSI Abrasion Level 3

WASHING INSTRUCTIONS

Remove all large particles. Rinse with cold water then machine wash in warm water with mild detergent or soap for 10-15 minutes. Water temperature should not exceed 160°F (71°C). Rinse in cold water. Tumble dry for 10-15 minutes, not exceeding 150°F (67°C). A diluted bleach solution may be used (5.25% sodium hypochlorite or 1:10 household bleach).

CAUTION

Gloves are cut resistant but are not cut or puncture-proof. Do not subject to high-speed, serrated blades or intentional slashings.

Wells Lamont Industrial

Toll-Free 1.800.247.3295 www.wellslamontindustrial.com