WELLS LAMONT

Industrial

PRODUCT SPECIFICATION SHEET



PRODUCT INFORMATION

Style: Silver Talon

Size Overedge Part # Sizing: XSmall 134525 Green Yellow Small 134526 Medium 134527 Blue Large 134528 White XLarge 134529 Orange XXLarge Black 135747

Registered Brand Name: Whizard®
Classification: Cut Resistant

PRODUCT DESCRIPTION

Description:High Performace Cut GloveColor:Gray Shell / Blue Wrist

Material: Patented Yarn Composition of High Performance Fibers and Stainless Steel

CFR21 - Approved for Food Contact

Latex Free

Packaging (Inner Pack): 6 Pieces
Packaging (Case Pack): 120 Pieces

CUT PROTECTION PERFORMANCE INFORMATION

Test Method: ASTM F2992-15
Test Results: 4,999 grams
ANSI Level A7

ABRASION PROTECTION PERFORMANCE INFORMATION

Test Method: ASTM D3884-09

Test Results: ANSI Level 3 1600 Cycles

CE EN 388 STANDARD

EN Abrasion Resistance: § 6.1 Level X
EN Cut Resistance: § 6.2 Level 4
EN Tear Resistance: § 6.3 Level 4
EN Puncture Resistance: § 6.4 Level 1

PARTICULATE TESTING INFORMATION

Test Method: Helmke Drum Particle Testing (IEST-RP-CC003.4, Appendix B, Section B.2.5)

Test Results: P>0.3µm/sq.ft. = Category III P>0.5µm/sq.ft. = Category III

WASHING INSTRUCTIONS

Remove all large particles. Rinse with cold water then machine wash in warm water with mild detergent or soap for 10-15 minutes. Water temperature should not exceed 160°F (71°C). Rinse in cold water. Tumble dry for 10-15 minutes, not exceeding 150°F (67°C). A diluted bleach solution may be used (5.25% sodium hypochlorite or 1:10 household bleach).

CAUTION

Gloves are cut resistant but are not cut or puncture-proof. Do not subject to high-speed, serrated blades or intentional slashings.

Wells Lamont Industrial

Toll-Free 1.800.247.3295 www.wellslamontindustrial.com