

## PRODUCT SPECIFICATION SHEET

### PRODUCT INFORMATION

**Style:** 5601

<b>Sizing:</b>	<b>Size</b>	<b>Part #</b>	<b>Overedge</b>
	XSmall	5601XS	Green
	Small	5601S	Yellow
	Medium	5601M	Blue
	Large	5601L	White
	XLarge	5601XL	Orange
	XXLarge	5601XXL	Black



**Classification:** Cut Resistant

### PRODUCT DESCRIPTION

**Description:** Gray High Performance Cut Glove  
**Gauge:** 15 Gauge  
**Material:** Combination of High Performance, Durable Fibers and Stainless Steel  
CFR 21 - Approved for Food Contact

**Packaging (Inner Pack):** 6 Pieces  
**Packaging (Case Pack):** 72 Pieces

### CUT PROTECTION PERFORMANCE INFORMATION

**Test Method:** ASTM F2992-15  
**Test Results:** 4,147 grams  
ANSI Level A7

### ABRASION PROTECTION PERFORMANCE INFORMATION

**Test Method:** ASTM D3884-09  
**Test Results:** ANSI Level 3, 1350 Cycles

### WASHING INSTRUCTIONS

Remove all large particles. Rinse with cold water then machine wash in warm water with mild detergent or soap for 10-15 minutes. Water temperature should not exceed 160°F (71°C). Rinse in cold water. Tumble dry for 10-15 minutes, not exceeding 150°F (67°C). A diluted bleach solution may be used (5.25% sodium hypochlorite or 1:10 household bleach).

### CAUTION

Gloves are cut resistant but are not cut or puncture-proof. Do not subject to high-speed, serrated blades or intentional slashings.

*Wells Lamont Industrial*  
Toll-Free 1.800.247.3295 [www.wellslamontindustrial.com](http://www.wellslamontindustrial.com)